

## KHALSA COLLEGE FOR WOMEN

(Reaccredited Grade 'B++' by NAAC)

SIDHWAN KHURD- 142024

DISTT-LUDHIANA (PB.)

Ref.No.ITEP/ A

Dated.28.01.2025

To

Regional Director  
Northern Regional Committee  
National Council for Teacher Education  
G-7 Sector 10 , Dwarka , New Delhi

**Subject : List of Documents Regarding ITEP**

Respected Sir

Building Safety Certificate Sub Division Engineer, Construction Sub Division,  
PWD (B&R) Government Of India, issued by the Competent Authority .

Principal,

Khalsa College for Women,  
Sidhwan Khurd (Ludhiana)

Phone:- 98788-94055(Principal Office), 01624-234967 (Administration Office)

Website: - kcwsidhwan.org, Email: - kcw\_sidhwan@rediffmail.com


# BUILDING SAFETY CERTIFICATE.

## Part-1

### Performa for the safety of School Building (To be filled by the head of School/Institute)

1. Name of School : **Khalsa College For Women, Sidhwan Khurd**
2. Location : **VPO- Sidhwan Khurd, Teh- Jagraon, Dist-Ludhiana**
3. Plot Area : **3699965 Sq.Ft**
4. Plinth Area : **1,40,388.17 Sq.Ft**
5. Number of Story : **Double Story**
6. Year of construction of building : **Started in 1950**
7. Supervision of the qualified Engineer  
The following details may be given:
  - a) Name of the Engineer : **ER. Pardeep Kumar Jain**
  - b) Set of drawing used in construction : **Attached.**
  - c) Name of Architect & address : **Gursewak Singh, H.O-407/12, Sherpura Road, Jagraon**
8. Whether the building has been constructed for the purpose of:
  - a) College (Yes/No) **Yes**
  - b) Residential purpose and converted  
For use as College (Yes/No) **NO**
9. Material used for Roof:
  - a) R.C.C Slabs (Yes/No) **Yes.**
  - b) R.S. Joists and Battens (Yes/No) **No**
  - c) Wooden joists and Battens (Yes/No) **No**
10. Material used for Walls:
  - a) Mud Mortar (Yes/No) **No**
  - b) Cement Mortar (Yes/No) **Yes**
  - c) Plaster
    - a) Lime Mortar **No**
    - b) Cement Mortar (Yes/No) **Yes**
11. Flooring:
  - a) Conglomerate (Yes/No) **No**
  - b) Terrazzo (Yes/No) **No**
  - c) Brick Paving (Yes/No) **Yes**
  - d) Marbal (Yes/No) **Yes**
12. Detailed Drawing indicating dimensions  
Of the rooms along with size and location  
Of doors and windows **Attached.**

*G. J. Singh*



Principal,  
Khalsa College for Women,  
Sidhwan Khurd (Ludhiana)

(To be filled by S.D.E of P.W.D. B&R Department)

Name of School: **Khalsa College for Women, Sidhwan Khurd Teh-Jagraon, Dist- Ludhiana**


I have visited the above mentioned College on **14/01/2025** and I have visually inspected it from all angles of safety and I found it fit for normal use as College building.


In case any addition/alteration of expansion and modification of this building is to be carried out the same be carried out under the supervision of a technically specified Engineer and this certificate may be obtained after the completion of the work from the under signed.

In case the building is affected by flood or if there is settlement of walls/foundations or caves of roof etc . immediately inspection of the undersigned be arranged or check the stability and safety of the building.

This building can be safely occupied for normal use up to Date...**26-02-2025**  
(Indicate year up to which it can be used).

(for year 2024-25)

  
14/01/2025

  
Sub Divisional Engineer  
Construction Sub Division  
PWD (B&R) Jagraon at Ludhiana

Endst. No:- **483-484**

Dated:- **16-01-2025**

Copy of the above is forwarded to the following for information:-

1. Principal, Khalsa College for women, Sidhwan Khurd Tehsil Jagraon Distt Ludhiana.
2. Executive Engineer, Construction Division No. 1, PWD B&R Ludhiana.

  
Sub Divisional Engineer  
Construction Sub Division  
PWD (B&R) Jagraon at Ludhiana